



d	M3	M4	M5	M6	M8	M10	M12
k max	2,4	3,2	4,7	5,2	6,8	8,4	10,8
S	5,5	7	8	10	13	16	18

d	M14	M16	M18	M20	M22	M24	M27
k max	12,8	14,8	15,8	18,0	19,4	21,5	23,8
S	21	24	27	30	34	36	41

d	M30	M33	M36	M39
k max	25,6	28,7	31,0	33,4
S	46	50	55	60